Outlook

Re: SID

From Colin Hardy <Gryffon@outlook.com>
Date Thu 2026-09-10 6:51 AM
To clerk@coddenham-pc.gov.uk <clerk@coddenham-pc.gov.uk>; Nick Mills <cllrnickmills@coddenham-pc.gov.uk>
Cc Ian Thompson <tomo1964@btinternet.com>

An agenda item in the November meeting would be fine. It is not urgent. It is only the data reporting that is not working on the SID the sign warning motorists of their speed is still working. So one option would be to wait until the device packs up completely and then consider whether the Parish Council wants to purchase a replacement and if so from whom.

Best wishes Colin

From: clerk@coddenham-pc.gov.uk <clerk@coddenham-pc.gov.uk>
Sent: Wednesday, 9 September 2026 19:40
To: Colin Hardy <gryffon@outlook.com>; Nick Mills <cllrnickmills@coddenham-pc.gov.uk>
Cc: Ian Thompson <tomo1964@btinternet.com>
Subject: Re: SID

Hi Colin
Any replacement, if bought by the parish council, would need to be discussed at council and the expenditure approved. The agenda for the next meeting has already been published so it would have to wait for the November meeting unless deemed urgent enough to amend and republish the agenda.
Apart from the organisation you mention, do you know of any other suppliers of SIDs which it would be worth approaching for a quote? I can do a Google search but if you're aware of any so much the better.

Kind Regards,
Maggie

From: Colin Hardy <gryffon@outlook.com>
Sent: 08 September 2026 7:28 PM
To: Maggie Burt <clerk.coddenhampc@gmail.com>; Nick Mills <cllrnickmills@coddenham-pc.gov.uk>
Cc: Ian Thompson <tomo1964@btinternet.com>
Subject: SID

I have just had useful conversation with Jill Taylor (Sales Category Manager- Signage, CMT Group), and told her about our problems with SID in terms of it now not down loading data through either of the USB ports or the Seriel port. She suggested:

1. Not worth trying to get it repaired on such an old machine. We would have to pay to get it back to Germany, and the repair fee.

2. As the warning messages are still working one option would be to leave the sign up until it stops working then consider whether we wish to purchase new sign, (eight years ago we paid over £2,000 so todays costs could be much higher).
3. They do make a range of devices if in the future we are interested including one that monitors 7 different types of vehicle including HGV and the speed, time etc. but has no sign.

□

Best
wishes,
Colin